



Acc	essory Package List				
No.	Spare part	No.	Spare part	No.	Spare part
A	x1	В	x1	С	x_1 x_1
No.	Spare part	No.	Spare part		
D	x2 x8 x4	Е	x1		









Assembly Step 3


Based on the actual usage, press the handle grips both sides simultaneously, and adjust the workstation to the proper height.





Please do not put hands near the supporting bars, as they change during adjusting and may hurt you.





△ WARNING

Hands Pinching



Do not place your hand near the strut. Strut's angle will change during the desktop lifts and it may hurt you.



Please do not put hands near the supporting bars, as they change during adjusting and may hurt you.






Please make sure all installed equipments are on the table, and not sticking out of the edge, or it may harm or cause damage.






Please leave enough length of cable for height adjustment function, otherwise it may cause unexpected lost.





Warning

Please first adjust it to the highest, then remove equipment to avoid harm or damage.





Warning

Please move it by two persons, or parts may collide and cause damage.

Produced in ChRL for:

DMTrade Mikołaj Tomaszewski Wiśniowa 36; 64-000 Kościan, Poland

NIP: PL 6981681757 sklep@dmtrade.pl

Tel.: +48 661082052 / +48 785082052